

## State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

July 15, 2015

Steve Schnoor Kennecott Utah Copper LLC 4700 Daybreak Parkway South Jordan, Utah 84095

Subject: Review of Clay Hollow Post-Removal Report, Kennecott Barneys Canyon Mining, Barneys

Canyon Mine, M/035/0009, Salt Lake County, Utah

Dear Mr. Schnoor:

On July 2, 2015 the Division of Oil, Gas and Mining (Division) received the Clay Hollow Post Removal Report Version 1.2 summarizing the restoration of the sediment release at Barneys Canyon. The Division has accepted this report and incorporated it into the Notice of Intention to Commence Large Mining Operations. A copy of the accepted report can be found on the Division's web site.

The Division recommends that remediation work continue as weather permits including buttressing and capping the leach pads.

The approval or acceptance of a complete notice of intention does not relieve an operator from his responsibility to comply with the applicable statutes, rules, regulations, and ordinances of all local, state and federal agencies with jurisdiction over any aspect of the operator's mining operations.

Please contact Leslie Heppler at 801-538-5257 or me at 801-538-5261 if you have questions about this action. Thank you for your cooperation.

Sincerely

Paul B. Baker

Minerals Program Manager

PBB: lah: eb

cc: Doug Bacon, Hans Millican, Brian Hamos, Dan Hall, and David Allison, DEQ (dbacon@utah.gov, hmillican@utah.gov, bhamos@utah.gov, dhall@utah.gov, dallison@utah.gov, Kerri Fiedler, EPA (fiedler.kerri@epa.gov)
P:\GROUPS\MINERALS\WP\M035-SaltLake\M0350009-BarneysCyn\Final\AMEND-6712-07132015.docx

